Brookhaven National Laboratory RADIOLOGICAL WORK PERMIT

Start Date: 8/1/04

RADIOLOGICAL WORK PERMIT
RWP # 04-01

□ Job Specific ■ Standing /General End Date: <u>7/31/05</u> (Shaded areas 1 through 8 to be completed by requestor/initiator) Revised End Date: 3. Phone: 5272 1. Initiator: Raymond Karol 2. Life #:15065 4. Bldg: 911 5. Job Location(s): Posted Radiation Areas at the Collider-Accelerator Department See SI(1) 6. Job Description (Attach sheets as needed): Routine Entry for Inspections, Data Collection, Tours, or Routine Work Activities Performed by a System Specialist. 6a. Work Begins: 08-01-04 6b. Work Ends: 07-31-05 7. Historical/Other Concerns: N/A 8. Signature of Initiator: Ray Karol Signature on file 9. Conditions that will void RWP: None 10. Job Review: 11. Estimated Dose: 12. Attachments: 13. Training Requirements: ■ Pre-Job Review Highest Individual: 20 mRem ■ Radiological Survey Form ■ Radiation Worker I (RWT 002) ☐ Contamination (RWT 300, 300A) □ Pre-Job Briefing □ Per Job (Posted locally) ■ Per Entry ☐ Technical Work Document □ GERT ■ Other: C-A Facility Specific Training, Collective: ■ Other: <u>Pre-Job Review</u> **Work Control Coordinator** 200 mRem (Access, Fixed Target, Radiobiology or Collider Users) in addition to Radiation to consult with Building ■ Per Job C-A OPM-ATT 9.5.4a Worker 1. □ Per Entry Manager and/or supervisor when assigning tasks. □ Not Applicable Entry into U-Line requires C-A Access or C-See SI (2) A-Fixed Target Training in addition to Radiation Worker 1. See SI(3) 14. Work Controls: 15. Protective Equipment: 16. Dosimetry: 17. Check Out Instructions: ■ TLD ☐ Facility Support Coverage ☐ Gloves **Many Locations Require** ☐ Shoe Covers □ Intermittent **Activation Checks Prior to** □ Coveralls □ Continuous ☐ Self Reading Dosimeter Removing Items from Area. ☐ Head Cover □ Pencil ■ Hold Points See SI (4) ☐ Red Trim Lab Coat □ Digital Read and Follow All Postings. □ Respirator ☐ Alarming Dosimeter □ Other: ■ Limiting Conditions See SI (5) ■ Not Applicable ☐ Finger Dosimetry ☐ Air Monitoring □ Shielding □ Not Applicable Other: See SI (6) 18. Special Instructions (SI): (Including Facility Specific Training) (1) Refer to C-A OPM-ATT 9.5.4a for a listing of permanent Radiation Areas. Due to the transient nature of many Radiation Areas at C-A there will be some that may not be listed on this attachment but may be covered under this RWP. Read and follow all postings. No single entry shall result in more than 20 mR. Multiple entries shall not result in more than 20 mR per person per job. If pre-job dose estimates exceed 20 mR per person or 200 mR collective a Job-Specific RWP is required. A trained and authorized C-A escort in accordance with C-A OPM 2.16 may escort visitors. (4) Consult with Facility Support Staff prior to starting any job in the U-line Neutrino Blockhouse (LANL proton radiography). (5) This RWP is not for work in Radiation Fields > 100 mR hr⁻¹, Handling or exposure to tritiated water, Unapproved alterations of radiation barriers, or for work with the potential to disperse or generate radioactive contamination. Review appropriate radiological survey prior to commencing work. The sign-in log for this RWP is located in the 911A Training Office, and the Health Physics Field Office after normal working hours. Life Number Department Date 19. Signatures Approvals: Facility Support Representative or Designee: Signature on file RCD 19773 Paul Bergh Other (Department Specific): C-A 14255 Edward T. Lessard Signature on file 20. Close-Out Signature (FS Representative):